



GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining


MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

March 07, 2013

Reviewed: 

Mine Name: Beck Street Quarry	Permit Number: M/035/0020
Operator Name: Lakeview Rock Products, Inc.	Inspection Date: September 30, 2009
Inspector(s): L Heppler	Time: 4:00 PM
Other Participants: Operator Representative – John Burgraff	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 11-01-2011 **Bond Amount:** \$363,100 **Permit fee** is up to date

Purpose of Inspection: Routine annual inspection. This site was last inspected as a large mine 12/05/2007, by Beth Ericksen.

Inspection Summary: NOI on file with the Division. Overall the Operation is well maintained - no erosional problems were noted, fence was maintained, no deleterious material was noted and roads were in good condition. Laydown storage was on edges of haul roads. Russian thistle was noted throughout the site. Every effort should be made to salvage top soil from the site prior to mining. There is a pending request for bond release by the Operator submitted on October 12, 2012.

Photos were taken to document site conditions.

Conclusions and Recommendations: Operator is past due for a periodic plan review, which includes a bond escalation review. The operator should make an effort to control weeds before they invade the mine site. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature _____

LAH:pb

cc: John Burgraff

O:\M035-SaltLake\M0350020-Lakeview\inspection\Insp-09302009.doc





Overview of upper mine site – looking south



Overview of upper mine site – looking south



Below upper mine site – looking south – note Russian Thistle




Overview of upper mine site – looking south – Blast pattern



Lower pit



Lower pit – note dozer slot, from upper pit



Lower pit



Lower pit



Floor of pit



Storage along haul road



Haul road on south side of lowr pit



Sediment pond